

ABC Cell Repairs Please ensure your document includes the highlighted information. If this information is not visible, the document may not be accepted.

10/18/2018 13:42 Store ID: 157890 Tel: (222)-333-4444

Repair Estimate

Please retain this document for your records.

Customer Information Joan Smith 123 Main Street Philadelphia, PA 12345 USA

(123)444-5555

Repair No. 321098765 Brand: ABC Wireless Co. Brand Model: 10XYZ

Problem Description/Diagnosis

Cracked screen; Touchscreen malfunctioning

Confirmed by Tech: Yes Cosmetic Condition: Shattered screen Resolution: Send to warehouse to remove and replace screen; restore functions of touchscreen

Employee ID: 98706540

Repair Estimate		
Item Number	Description	Cost
321098765	White, 35mm ABC Brand Model 10XYZ cell phone with LCD touchscreen	\$400.00
	Total (Tax not in	ncluded) \$400.00

By signing below, I agree to the following:

- ABC Cell Repairs is not responsible for any loss or corruption of data that may occur during service; and
- The Terms and Conditions on the next page of this Work Authorization are applicable to the service of my product.

Customer Name:		eceived By:
Customer Signature:		Date: